Thursday, 2/9/2006 1:49:23 PM

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** : 25767

: 10323

P.O. Number

Al4:

This Issue

: 2/9/2006

S.O. No. : NA

Prsht Rev. First Issue : NC

: N/A : 25584

Type

: MACHINED PARTS

Part Number

Drawing Name

: K10008

Drawing Number

: D2432 REV F3

: BEARPAW KIT (19"X24")

Project Number

: N/A

Drawing Revision Material

: F3 : NA

Due Date

: 2/25/2006

Qty:

10 Um:

Each

Written By

Previous Run

Checked & Approved By

Comment

Blank size changed KJ/JLM

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Photocopy bluefile:

K10008

D206-559-013

D350-578-011 D315-670-011

D427-659-011

and create labels per PPP K10008 CHG006(Bag Bluefiles separately)

K3 06.03-93

2.0

MUHMWB10

UHMW 1" Black



Comment: Qty.:

6.8250 sf(s)/Unit Total: 68.2500 sf(s)

blank: 19.500" x 24.00" x 1.00" thick (+0.030/-0.000) per DSK086-5

Material: Black UHMW 1"

(MUHMWB10)

Batch: M/00 4/7

06/03/24

10

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1



Comment: HAAS CNC VERTICAL MACHINING #1

Note:(2) bearpaws for (1) Kit

1-Inspect material for defects or damage prior to machining

2-Machine as per Folio and Dwg D2432 Identify as D2432F

AN 06/03/24 JF. 06/03/26

10

3-Deburr

Dart Ae	rospace	e Ltd					
W /O:			WORK ORDER CHA	NGES			
DATE	STEP	PROC	EDURE CHANGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,		
Part No	:	PAR #:	_ Fault Category:	NCR: Yes	lo DQA:_	Date: _	
				QA: N/	C Closed: _	Date: _	
NCR:		W	ORK ORDER NON-CONFOR	MANCE (NCR))	[
DATE	OTED	Description of NC		Section B	Verification	on Approval	Approval
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng	on Sign & Date	Section C		QC Inspector
			•			İ	
		_					
	,	,					
				:		,	

Thursday, 2/9/2006 1:49:24 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 25767 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC2 6/03/26 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 5.0 QC8 Comment: SECOND CHECK PACKAGING RESOURCE #1 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit Neoprene Cushion-.750 bl 7.0 D2182B 0.4166 f(s)/Unit Total: Comment: Qty.: 4.1660 f(s) Pick: Packing Kit Qty Part Number Description Batch Rubber Cushion _b 24970 6 D2182B050 M.6-D2274 Radius Block 8.0 Comment: Qty.: 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch Radius Block 135769 12 D2274 Bearpaw 2567 2 D2432F(ref only) D2438 Clamp 9.0 Comment: Qty.: 6.0000 Each(s)/Unit Total: 60.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch Clamp B 25015. 6 D2438

Dart Aerospace Ltd

W/O:		WORK ORDER CH					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						 - 	
	~ 6 .		· .				
Part No		PAP #: Fault Catagony	NCD: Vee	50		Datas	

QA: N/C Closed: ____ Date: ____

NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Varification		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspecto
							i ·	
,		-						
					,			
						!		
						į		
						i		1

Date: Thursday, 2/9/2006 1:49:24 PM User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 25767 Job Number: Description: Seq. #: Machine Or Operation: Washer D2529 10.0 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch Washer 13 25 372 12 D2529 M.F. 06.03.27 Rubber Extrusion 11.0 D2732 Comment: Qty.: 4.1660 Each(s) 0.4166 Each(s)/Unit Total: Pick: Packing Kit Qty Part Number Description Batch 6 D2732-050 Rubber Cushion **B04/82** M.F. 06.03.27 Bolt 12.0 AN415A Comment: Qty.: 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch M19085 m.F. 06.03.27 Bolt 12 AN4-15A Bolt 13.0 AN417A 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch Bolt M15432. 12 AN4-17A m.f. 06.03.27. 14.0 AN960JD416 Washer 24.0000 Each(s)/Unit Total: 240.0000 Each(s) Comment: Qty.: Pick: Packing Kit 10 Qty Part Number Description Batch Washer <u>M1908</u>5 24 AN960JD416 M.F 06.03.27

Dart Aerospace Ltd

W/O:		WORK ORDER CH	ANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<u> </u>			\bigcirc			, ,

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date: <u>06/03/2</u> 5
			QA: N/C Closed:	Date:

NCR:		,	WORK ORD	ER NON-CONFORMAN	CE (NCR)			
D.4.77		Description of NC		Corrective Action Section B	}	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		GON CHO	G887.73	Action Description Chief Eng				
		•						
						:		

Thursday, 2/9/2006 1:49:24 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: BEARPAW KIT (19"X24") Customer: CU-DAR001 Dart Helicopters Services Part Number: K10008 Job Number: 25767 Job Number: Seq. #: Description: **Machine Or Operation:** MS21042L4 Nut 15.0 12.0000 Each(s)/Unit Total: 120.0000 Each(s) Comment: Qty.: Pick: Packing Kit Qty Part Number Description Batch M19099 12 MS21042L4 -Nut (or -4) QC4 16.0 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE # PACKAGING 1 17.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPPK10008 Location: 8 DOCUMENT CONTROL 18.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Dart Aerospace Ltd

Dait Ac	ospace	Lu					!	
W/O:			W	ORK ORDER CHANG	SES		 	
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				£				
		• ,						
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes 1	No DQA:	Date: _	
						C Closed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC			ion B	Verification		Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		·						
								·
								,
				,				

DART AEROSPACE LTD	Work Order:	25767
Description: Bearpaw	Part Number:	D2432
Inspection Dwg: D2432 Rev: F3		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	pection Sheet ving Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Α	0.063 x 45°	+0.030/-0.010	0.055				
В	5.500	+/-0.030	5, 499	/			
С	0.200	+/-0.030	0.199				
D	0.25 x 45°	+/-0.030	0,247				
Е	.∗R0.250	+/-0.030	R0.250				
F	0.250	+/-0.010	0.253				
G	0.625	+/-0.030	0.635	-			
Н	0.375	+/-0.010	0,383				
I	0.950	+0.030/0.010	10.951				
J	19.000	+/-0.030	19.000				
K	3.14	+/-0.030	3.140				
L	3.28	+/-0.030	3.278				
М	Ø0.260	+0.005/-0.000	80.260				
N	Ø0.93	+/-0.030	00.930				
0	0.30	+0.030/-0.000	0.324				
Р	23.750	+/-0.030	23.750				
Q	7.375	+/-0.030	7.375				
R	4.250	+/-0.010	4.250	_			
S	2.000	+/-0.030	2.000				
Т	9.000	+/-0.010	9.000				
U	9.000	+/-0.010	9.000				
٧	0.375	+/-0.010	0.381				

Measured by:	gm/	Audited by:	En	Prototype Approval:	N/A
Date:	06/03/24	Date:	06/03/24	Date:	NIA


Rev	Date	Change	Revised by	Approved
Α	04.01.09	New Issue	KJ/RF	








DESIGN	DRAWN BY		OSPACE LTD ONTARIO, CANADA
CHECKED	APPRO ED	DRAWING NO.	REV. F
1 800 -	(4)	D2432	SHEET 2 OF 2
DATE		TITLE	SCALE
98.05.12		BEARPAW	1:4





SECTION C-C

SHOP COPY RETURN TO ENGINEERING

UNCONTROLLED CO

SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER NO. 25767

Copyright 1995 by DART AEROSPACE LTD